
# SOUND ABSORPTION AREA FOR OBJECT

Measured and evaluated according to ISO 354 and ISO 20189

| | | | |
|---|---|---|---|
| **Client:** | Boom Interior | | |
| **Object:** | Xrozz Absorption Recycled | | |
| **Size [mm]:** | w = 600 | h = 1600 | d = 40 |

| Octave band (Hz) | Equivalent sound absorption area / unit ($m^2$Sabine) |
|---|---|
| 63 | 0.3 |
| 125 | 0.37 |
| 250 | 0.68 |
| 500 | 0.88 |
| 1000 | 1 |
| 2000 | 1.22 |
| 4000 | 1.48 |
| $N_{10}$ = | 11.4 |




| ORIGINAL TEST REPORTS | DATE OF REPORT |
|---|---|
| Akustikverkstan report 18-701-M2a | 2018-08-23 |
| Akustikverkstan report 18-701-M3 | 2018-08-23 |

*The presented results are interpolated using the method described in ISO 20189 from the original test reports.*

**Acoustic Facts Scandinavia AB**

Kinnegatan 23, 531 33 Lidköping

acousticfacts.com