
# SOUND ABSORPTION AREA FOR OBJECT

Measured and evaluated according to ISO 354 and ISO 20189

| | | | |
|---|---|---|---|
| **Client:** | Kinnarps | | |
| **Object:** | Rezon with RZLA | | |
| **Size [mm]:** | w = 1200 | h = 1785 | d = 60 |

| Octave band (Hz) | Equivalent sound absorption area / unit ($m^2$Sabine) |
|---|---|
| 63 | 0.2 |
| 125 | 0.78 |
| 250 | 1.37 |
| 500 | 2.54 |
| 1000 | 2.93 |
| 2000 | 2.93 |
| 4000 | 3.32 |
| $N_{10}$ = | 3.9 |




| ORIGINAL TEST REPORT | DATE OF TEST |
|---|---|
| SP report P805772BE | 2013-11-05 |

**Acoustic Facts Scandinavia AB**

Kinnegatan 23, 531 33 Lidköping

acousticfacts.com